

Internal
S/031/0009



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
January 6, 2010

Reviewed:

| | |
|---|--------------------------------------|
| Mine Name: Kingston Canyon Rock | Permit Number: S/031/0009 |
| Operator Name: Utah Wildlife Resources | Inspection Date: June 2, 2009 |
| Inspector(s): Lynn Kunzler | Time: 3:00 pm |
| Other Participants: None | Mine Status: Active |

| Elements of Inspection | Evaluated | Comment | Enforcement |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection:

Routine Inspection while in the area

Inspection Summary:

Permit fees are up to date. There is no surety bond requirement for this site due to the operator being a sister (DNR) agency. At the time of permitting, the Associate Director had determined that it was not necessary to bond another DNR agency since if there was a default and the Division needed to do the reclamation, it would have access to the necessary funds from the permitted agency.

While no activity was being conducted at the time of this inspection, there was evidence that there has been recent activity. The site was stable and free of garbage.

Conclusions and Recommendations:

This area appears to be in compliance at this time. There was no trash or garbage observed and there were no erosion problems noted. Continue to monitor this site when in the area

Inspector's Signature

cc: Stan Beckstrom, DWR-Cedar City
John Blake, SITLA

O:\M031-Piute\S0310009-kingstonCyn\inspections\Insp06022009.doc